

FIG. 1A-1 $\text{PFC/PC} = 0$




FIG. 1A-2



FIG. 1B-1 $\text{PFC/PC} = 1.1$



FIG. 1B-2



FIG. 1C-1 $\text{PFC/PC} = 2.2$




FIG. 1C-2




FIG. 1D-1



FIG. 1D-2




FIG. 1E-1




FIG. 1E-2




FIG. 1F-1




FIG. 1F-2

PFC/PC = 44.7






FIG. 2




T = 0

FIG. 3A




30 Sec

FIG. 3B



1 Min

FIG. 3C



2 Hrs

FIG. 3D